



Snap Indicators



“Shift Right Click” Osnap Flyout



You can also type overrides in during a command at the prompt to Force a specific snap:

END
MID
CEN
NOD
QUA
INT
PER
TAN
NEA